


View of a whole wall tamped in three layers
This wall has not yet been finished or water
proofed. On top the rears that fix the wood
tie beam to the earth wall can be seen.



A view of an interior adobe
wall shot through a window.
This wall does not yet have
a finish on it.